SITE ID	LOCATIONAL IDENTIFIER	2nd Address	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	BUILDING TYPE	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
001-0000-01	P.O. BOX 217		N																						
001-0001-00	100 MAIN STREET	P.O. BOX 217	N	C	N	3/4"	1970	C	3/4"	1970	NONRES	N	CLS		1970		Field inspection only	N	5/9/24	Cross-connection survey	Field inspection only	Y	5/9/24	Cross-connection survey	Copper/Copper
001-0001-01	409 N STREET		N																						
001-0002-00	100 MAIN STREET	P.O. BOX 217	N	P	N	2"	1935	P	2"	1935	NONRES	N	O			Galvanized pipe	Field inspection only	N	5/9/24	Cross-connection survey	Field inspection only	Y	5/9/24	Cross-connection survey	2" Galvanized/Black pipe
001-0003-00	105 MAIN STREET	P.O. BOX 217	N	C	N	3/4"	1935	C	3/4"	1935	NONRES	N	CLS		1935		Field inspection only	N	5/10/24	Cross-connection survey	Field inspection only	Y	5/10/24	Cross-connection survey	Copper/Copper
001-0004-00	100 MAIN STREET	P.O. BOX 217	N																						
001-0005-00	100 MAIN STREET	P.O. BOX 217	N																						
001-0007-00	109 MAIN STREET	P.O. BOX 217	N	C	N	3/4"	1935	C	3/4"	1935	NONRES	N	CLS		1935		Field inspection only	N	5/10/24	Cross-connection survey	Field inspection only	Y	5/10/24	Cross-connection survey	Copper/Copper
001-0008-00	113 MAIN STREET	P.O. BOX 116	N	C	N	3/4"	1935	C	3/4"	1935	SF	Y	CLS		1935		Field inspection only	N	3/21/24	Cross-connection survey	Field inspection only	Y	3/21/24	Cross-connection survey	Copper/Copper
001-0010-00	200 MAIN STREET	PO BOX 393	N	C	N	3/4"	1935	C	3/4"	1935	NONRES	N	CLS		1935		Field inspection only	N	2/8/23	Cross-connection survey	Field inspection only		2/8/23	Cross-connection survey	copper/copper
001-0011-00		P O BOX 393	N	C	N	3/4"	1935	C	3/4"	1935	MF	N	CLS		1935		Field inspection only	N	2/8/23	Cross-connection survey	Field inspection only		2/8/23	Cross-connection survey	copper/copper
001-0012-00	117 MAIN STREET	PO BOX 71	N	C	N	3/4"	1935	C	3/4"	1935	NONRES	N	CLS		1935		Field inspection only	N	12/5/23	Cross-connection survey	Field inspection only	Y	12/5/23	Cross-connection survey	copper/copper
001-0013-00	104 WALNUT STREET	P.O. BOX 554	N	C	N	1"	1935	P	1"	1935	SF	N	O				Field inspection only	N	3/6/24	Cross-connection survey	Field inspection only	Y	3/6/24	Cross-connection survey	plastic/pex
001-0014-00	614 1ST STREET		N	C	N	3/4"	1935	C	3/4"	1935	SF	N	CLS		1935		Field inspection only	N	12/4/23	Cross-connection survey	Field inspection only	Y	12/4/23	Cross-connection survey	copper/plastic -copper
001-0015-00	704 1ST STREET	PO Box 491	N	C	N	3/4"	1935	C	3/4"	1935	SF	N	CLS		1935		Field inspection only	N	3/4/24	Cross-connection survey	Field inspection only	Y	3/4/24	Cross-connection survey	Copper/Copper
001-0017-00	708 1ST STREET	P.O. BOX 365	N																						
001-0018-00	206 HEMLOCK STREET	P.O. BOX 647	N	C	N	1"	1935	C	1"	1935	NONRES	N	CLS		1935		Field inspection only	N	3/18/24	Cross-connection survey	Field inspection only	Y	3/18/24	Cross-connection survey	copper/copper
001-0019-00	201 WALNUT STREET	P.O. BOX 358	N	C	N	1"	1935	C	1"	1935	SF	N	CLS		1935		Field inspection only	N	9/29/22	Cross-connection survey	Field inspection only	Y	9/29/22	Cross-connection survey	Copper/Copper
001-0020-00	200 WALNUT STREET	PO BOX 82	N																						
001-0021-00	PO BOX 104		N																						
001-0023-00		P.O. Box 250	N																						
001-0024-00	PO BOX 65		N	C	N	3/4"	1935	C	3/4"	1935	NONRES	N	CLS				Field inspection only	N	2/8/23	Cross-connection survey	Field inspection only	Y	2/8/23	Cross-connection survey	copper/copper
001-0025-00	P.O. BOX 143		N																						
001-0026-00	711 SECOND STREET		N																						
001-0027-02	PO BOX 504		N	C	N	1"	1935	C	1"	1935	NONRES	N	CLS				Field inspection only	N	1/18/23	Cross-connection survey	Field inspection only	Y	1/18/23	Cross-connection survey	copper/copper
001-0027-03	312 WALNUT STREET	PO BOX 223	N																						
001-0027-04	AIR RUNNER NETWORKS, LLC	PO BOX 557	N																						
001-0027-05	216 MAIN STREET APT. A	PO BOX 330	N																						
001-0027-06	216 1/2 MAIN STREET	P.O. BOX 4	N																						
001-0028-00	151300 State Park Rd		N	C	N	3/4"	1935	C	3/4"	1935	NONRES	N	CLS		1935		Field inspection only	N	1/18/23	Cross-connection survey	Field inspection only	Y	1/18/23	Cross-connection survey	copper/copper
001-0029-00	304 MAIN ST	PO BOX 605	N	C	N	1"	1935	C	1"	1935	NONRES	N	CLS		1935		Field inspection only	N		Cross-connection survey	Field inspection only	Y		Cross-connection survey	copper/copper
001-0029-02	C/O STEPHANIE LEMMER	PO BOX 574	N	C	N	1"	1935	C	1"	1935	NONRES	N	CLS		1935		Field inspection only	N		Cross-connection survey	Field inspection only	Y		Cross-connection survey	coipper/copper
001-0033-00	307 MAIN ST		N	C	N	3/4"	1935	C	3/4"	1935	SF	N	CLS		1935		Field inspection only	N	3/18/24	Cross-connection survey	Field inspection only	Y	3/18/24	Cross-connection survey	Copper/Copper
001-0034-00	301 Main St	P.O. BOX 423	N	C	N	1"	1935	C	1"	1935	NONRES	N	CLS		1935		Field inspection only	N	5/3/24	Cross-connection survey	Field inspection only	Y	5/3/24	Cross-connection survey	Copper/Copper
001-0035-00	608 2nd Street		N	C	N	3/4"	1935	C	3/4"	1935	SF	N	CLS		1935		Field inspection only	N		Cross-connection survey	Field inspection only	Y		Cross-connection survey	copper/copper
001-0036-00	612 2ND STREET	P.O. BOX 312	N	C	N	3/4"	1935	C	3/4"	1935	SF	N	CLS		1935		Field inspection only	N	3/7/24	Cross-connection survey	Field inspection only	Y	3/7/24	Cross-connection survey	copper/copper-pex
001-0037-00	704 2ND STREET	P.O. BOX 452	N	C	N	3/4"	1935	C	3/4"	1935	SF	N	CLS		1935		Field inspection only	N	3/12/24	Cross-connection survey	Field inspection only	Y	3/12/24	Cross-connection survey	Copper/Copper
001-0038-00	712 2ND STREET	P.O. BOX 647	N	C	N	3/4"	1935	C	3/4"	1935	NONRES	N	CLS		1935		Field inspection only	N	3/18/24	Cross-connection survey	Field inspection only	Y	3/18/24	Cross-connection survey	Copper/Copper
001-0039-00	203 Hemlock Street	PO Box 524	N	C	N	3/4"	1935	C	3/4"	1935	SF	N	CLS				Field inspection only	N	12/19/2023	Cross-connection survey	Field inspection only	Y	12/19/2023	Cross-connection survey	copper/copper
001-0040-00	711 2ND STREET	P.O. BOX 125	N																						
001-0041-00	PO BOX 347	801 2ND STREET	N	C	N	3/4"	1935	C	3/4"	1935	SF	N	CLS				Field inspection only	N	2/2/2024	Cross-connection survey	Field inspection only	Y	2/2/2024	Cross-connection survey	Copper/Copper
001-0042-00	805 2nd Street	PO Box 241	N																						
001-0043-00	804 2ND STREET		N	C	N	3/4"	1935	P	3/4"	1935	SF	N	CLS				Field inspection only	N	2/9/24	Cross-connection survey	Field inspection only	Y	2/9/24	Cross-connection survey	Copper/Pex, Copper, Galv.
001-0044-00	811 2ND STREET	P.O. BOX 84	N																						
001-0045-00	812 2ND STREET		N	C	N	1"	1935	C	1"	1935	SF	N	CLS		1935		Field inspection only	N	10/6/22	Cross-connection survey	Field inspection only	Y	10/6/22	Cross-connection survey	Copper/Copper
001-0046-00	207 PINE ST		N	C	N	1"	1935	C	1"	1935	NONRES	N	CLS				Field inspection only	N		Cross-connection survey	Field inspection only	Y		Cross-connection survey	copper/copper
001-0048-00	PO BOX 217		N																						
001-0048-01	PO BOX 217		N																						
001-0048-02	PO BOX 217		N																						
001-0049-00	308 PINE ST		N																						
001-0050-00	PO BOX 320	500 COUNTY HWY S	N	C	N	3/4"	1935	C	3/4"	1935	NONRES	N	CLS		1935		Field inspection only	N	3/13/24	Cross-connection survey	Field inspection only	Y	3/13/24	Cross-connection survey	copper/copper pex
001-0050-01	PO BOX 320	500 CTY HWY ST	N	C	N	3/4"	1935	C	3/4"	1935	NONRES	N	CLS		1935		Field inspection only	N	3/13/24	Cross-connection survey	Field inspection only	Y	3/13/24	Cross-connection survey	copper/copper pex
001-0051-00	816 3RD STREET	PO BOX 253	N																						
001-0052-00	400 PINE STREET	P.O. BOX 404	N	C	N	1"	1935	C	1"	1935	NONRES	N	CLS		1935		Field inspection only	Y	1/18/23	Mech excav	Field inspection only	Y	1/18/23	Cross-connection survey	copper/copper
001-0053-00	812 3RD STREET	P.O. BOX 52	N	C	N	3/4"	1935	L	3/4"	1935	SF	N	CLS		1935		Field inspection only	N	2/1/24	Cross-connection survey	Field inspection only	Y	2/1/24	Cross-connection survey	Copper/Copper
001-0054-00	808 3RD STREET		N																						
001-0055-00	P.O. BOX 624		N	C	N	3/4"	1935	P	3/4"	1935	MF	N	CLS		1935		Field inspection only	N	5/28/24	Cross-connection survey	Field inspection only	Y	5/28/24	Cross-connection survey	Copper/Copper Pex in both units
001-0055-01	804 1/2 3RD STREET	PO BOX 372	N																						
001-0057-00	711 3RD STREET	P.O. BOX 188	N	C	N	1 1/2"		C	1 1/2"		NONRES	N	CLS				Field inspection only	Y	2/1/23	Cross-connection survey	Field inspection only	Y	2/1/2023	Cross-connection survey	Copper/Copper
001-0058-00	705 3RD STREET	P.O. BOX 455	N																						
001-0059-00	703 3RD STREET	P.O. BOX 322	N																						
001-0060-00	311 WALNUT STREET	P.O. BOX 487	N																						
001-0060-01	712 3RD STREET	P.O. BOX 487	N	DI	N	12"	2000	DI	12"	2000	NONRES	N	C		2000		Field inspection only	Y	3/6/24	Cross-connection survey	Field inspection only	Y	3/6/24	Cross-connection survey	ductal/copper
001-0061-00	305 WALNUT ST		N	C	N	3/4"	1935	C	3/4"	1935	NONRES	N	CLS		1935		Field inspection only	N	4/8/24	Cross-connection survey	Field inspection only	Y	4/8/24	Cross-connection survey	Copper/Copper
001-0061-01	312 WALNUT STREET	PO BOX 223	N	C	N	1"	1935	C	1"	1935	NONRES	N	CLS		1935		Field inspection only	N	12/18/23	Cross-connection survey	Field inspection only	Y	12/18/23	Cross-connection survey	copper/copper
001-0061-02	415 WALNUT STREET		N																						
001-0062-00	1302 6TH STREET		N	C																					
001-0063-00	608 3RD STREET	PO BOX 305	N	C	N	1"	1935	P	1"	1935	NONRES	N	O				Field inspection only	N	06/05/2024	Cross-connection survey	Field inspection only	Y	6/5/2024	Cross-connection survey	Copper / Pex in House
001-0064-00	315 MAIN STREET	P.O BOX 428	N																						
001-0065-00	Ashley Sternweis	523 N. 8th Avenue	N	C	N	3/4"	1935	C	3/4"	1935	NONRES	N	CLS				Field inspection only	N	1/26/2023	Cross-connection survey	Field inspection only	Y	1/26/2023	Cross-connection survey	copper/copper
001-0066-00	146250 COUNTY ROAD N		N	C	N	3/4"	1935	P	3/4"	1935	MF	N	CLS		1935		Field inspection only	N	1/2/24	Cross-connection survey	Field inspection only	Y	1/2/24	Cross-connection survey	copper/Galv-pex
001-0067-00	323 MAIN STREET		N	C	N	3/4"	1935	C	3/4"	1935	NONRES	N	CLS				Field inspection only	N	2/1/23	Cross-connection survey	Field inspection only	Y	2/1/23	Cross-connection survey	copper-copper
001-0068-00	314 MAIN ST	P.O. BOX 458	N	C	N	2"	1935	C	2"	1935	NONRES	N	CLS				Diameter > 2 inches	N	1/18/24	Cross-connection survey	Diameter > 2 inches	Y	1/18/24	Cross-connection survey	2" Copper/Copper
001-0070-00	C/O Capturis.com	PO Box 5590	N	C	N	3/4"	1935	C	3/4"	1935	NONRES	N	CLS				Field inspection only	N	3/20/24	Cross-connection survey	Field inspection only	Y	3/20/24	Cross-connection survey	copper/copper
001-0071-00	318 MAIN STREET	P.O. BOX 392	N																						
001-0074-00	PO BOX 5651		N	C	N	1"	1935	C	1"	1935	NONRES	N	CLS		1935		Field inspection only	Y	1/24/23	Mech excav	Field inspection only	Y	1/24/23	Cross-connection survey	copper/copper
001-0081-00	500 MAIN STREET	PO BOX 176	N	C	N	3/4"	1935	C	3/4"	1935	NONRES	N	CLS		1935		Field inspection only	N	2/2/23	Cross-connection survey	Field inspection only	Y	2/2/23	Cross-connection survey	copper/copper
001-0082-00	504 MAIN STREET	PO BOX 222	N																						
001-0083-00	508 MAIN STREET	P.O. BOX 23	N																						
001-0084-00	UTOPIA DAY SPA	845 W. BRUCKER STREE	N	C	N	3/4"	1935	C	3/4"	1935	NONRES	N	CLS				Field inspection only	N	2/7/24	Cross-connection survey	Field inspection only	Y	2/7/24	Cross-connection survey	Copper / Copper
001-0085-00	8317 Appaloosa Lane		N																						
001-0086-00	8317 Appaloosa Lane		N																						
001-0087-01	1941 PRAIRIE STREET		N																						
001-0088-00	604 4TH STREET	PO BOX 562	N																						
001-0089-00	PO BOX 485		N	C	N	3/4"	1935	C	3/4"	1935	NONRES	N	CLS				Field inspection only	N	2/1/23	Cross-connection survey	Field inspection only	Y	2/1/23	Cross-connection survey	copper/copper Pex
001-0090-00	509 WALNUT STREET		N																						
001-0091-00	701 4TH ST	PO BOX 373	N	C	N	3/4"	1935	C	3/4"	1935	SF	Y	CLS				Field inspection only	Y	2/6/24	Cross-connection survey	Field inspection only	Y	2/6/24	Cross-connection survey	Copper/Copper Pex
001-0092-00	709 4TH STREET	P.O. BOX 394	N																						
001-0093-00	508 HEMLOCK ST		N																						
001-0094-00	501 HEMLOCK STREET APT. A	PO BOX 656	N																						
001-0094-01	501 HEMLOCK ST		N	C	N	3/4"	1935	C	3/4"	1935	MF	N	O				Field inspection only	N		Cross-connection survey	Field inspection only	Y		Cross-connection survey	copper/pex

001-0095-00 400 PINE STREET	P.O. BOX 404	N																				
001-0096-00 406 PINE STREET	P.O. BOX 404	N	C	N	3/4"	1935	C	3/4"	1935	NONRES	N	CLS		Field inspection only	Y	6/1/23	Mech excav	Field inspection only	Y	2/1/22	Cross-connection survey	Copper/Copper Pex
001-0097-00 504 PINE STREET	P.O. BOX 351	N																				
001-0098-00 501 PINE STREET	P.O. BOX 402	N																				
001-0099-00	P.O. BOX 250	N	C	N	3/4"	1935	C	3/4"	1935	NONRES	N	CLS		Field inspection only	N	2/2/23	Cross-connection survey	Field inspection only	Y	2/2/23	Cross-connection survey	copper/copper
001-0100-00 148614 BURMA ROAD		N																				
001-0101-00 504 OAK STREET		N																				
001-0102-00 909 5TH STREET	P.O. BOX 389	N																				
001-0103-00 908 6TH STREET	P.O. BOX 306	N																				
001-0104-00 909 6TH STREET		N																				
001-0105-00 1005 6TH STREET		N																				
001-0106-00 P.O. BOX 95	1000 6th Street	N																				
001-0107-00 605 OAK STREET	PO BOX 292	N																				
001-0108-00 1005 5TH STREET		N																				
001-0109-00 RH APARTMENT RENTALS LLC	139999 HIGHLAND DRIVI	N																				
001-0110-00 1003 4TH STREET		N																				
001-0111-00 908 4TH STREET		N																				
001-0112-00 1002 4TH STREET		N	C	N	3/4"	1935	C	3/4"	1935	SF	N	CLS	1935	Field inspection only	N	4/8/24	Cross-connection survey	Field inspection only	Y	4/8/24	Cross-connection survey	Copper/Copper
001-0112-01 1006 4TH STREET		N																				
001-0113-00 1008 4TH STREET		N																				
001-0114-00 1102 4TH STREET		N																				
001-0115-00	1007 4TH ST	N																				
001-0116-00 1008 5TH STREET		N	C	N	1"	1970	C	1"	1970	SF	N	CLS	1970	Field inspection only	N	2/25/22	Cross-connection survey	Field inspection only	Y	2/25/22	Cross-connection survey	Copper/Copper
001-0117-00 1007 5th STREET		N																				
001-0118-00 604 SPRUCE STREET	PO BOX 171	N																				
001-0119-00 1006 6TH STREET		N																				
001-0120-00 1007 6TH STREET	P.O. BOX 545	N																				
001-0121-00 702 HEINDL LANE		N																				
001-0122-00 802 HEINDL LANE	P.O. BOX 415	N																				
001-0123-00 804 HEINDL LANE		N	C	N	1"	1970	C	1"	1970	SF	N	CLS	1970	Field inspection only	N	10/26/22	Cross-connection survey	Field inspection only	Y	10/26/22	Cross-connection survey	Copper/Copper
001-0124-00 1002 8TH ST		N	C	N	1"	1970	C	1"	1970	SF	N	CLS	1970	Field inspection only	N	2/10/22	Cross-connection survey	Field inspection only	Y	2/10/22	Cross-connection survey	Copper/Copper
001-0125-00 1005 8TH STREET		N																				
001-0126-00 1007 8TH STREET		N																				
001-0127-00 1009 8TH STREET		N																				
001-0128-00 1011 8TH STREET		N																				
001-0129-00 1013 8TH STREET		N																				
001-0130-00 1101 8TH STREET		N																				
001-0131-00 1103 8TH STREET	P.O. BOX 555	N	C	N	1"	1970	C	1"	1970	SF	Y	CLS	1970	Field inspection only	N	2/12/24	Cross-connection survey	Field inspection only	Y	2/12/24	Cross-connection survey	Copper/Copper
001-0132-00 1107 8TH STREET		N	C	N	1"	1990	C	1"	1990	SF	N	C	1990	Installed after lead ban	Y	1990	Visual insp during install or repair	Field inspection only	Y	1/16/24	Cross-connection survey	Copper/Copper
001-0133-00 1109 8TH STREET	P.O. BOX 194	N																				
001-0134-00 1113 8TH STREET		N																				
001-0135-00 1106 8TH ST		N																				
001-0136-00 1108 8TH STREET		N																				
001-0139-00 1102 8TH STREET	P.O. BOX 535	N																				
001-0140-00 801 CHERRY STREET		N																				
001-0141-00 1012 8TH STREET		N																				
001-0142-00	1010 8th STREET	N																				
001-0143-00 1008 8TH STREET	P.O. BOX 22	N	C	N	1"	1970	C	1"	1970	SF	N	CLS	1970	Field inspection only	N	2/15/24	Cross-connection survey	Field inspection only	Y	2/15/24	Cross-connection survey	Copper/Copper
001-0144-00 809 HEINDL LANE		N																				
001-0145-00 807 HEINDL LANE		N																				
001-0146-00 3902 MILWAUKEE ST #S560	PO BOX 7188	N	C	N	1"	1970	P	1"	1970	SF	N	CLS	1970	Field inspection only	N	12/7/23	Cross-connection survey	Field inspection only	Y	12/7/23	Cross-connection survey	plastic/copper
001-0147-00 1011 HEINDL LANE		N																				
001-0148-00 1013 HEINDL LANE		N	C	N	1"	1970	C	1"	1970	SF	N	CLS	1970	Field inspection only	N	10/5/2023	Cross-connection survey	Field inspection only	Y	10/5/2023	Cross-connection survey	copper/Copper
001-0149-00 811 CHERRY STREET	P.O. BOX 376	N																				
002-0152-00 1107 HEINDL LANE		N																				
002-0153-00 1109 MERLIN COURT		N	C	N	1"	1970	C	1"	1970	SF	N	CLS	1970	Field inspection only	N	10/24/22	Cross-connection survey	Field inspection only	Y	10/24/22	Cross-connection survey	Copper/Copper
002-0155-00 1111 MERLIN COURT	P.O. BOX 307	N																				
002-0158-00 1110 MERLIN COURT		N																				
002-0158-01 1108 MERLIN COURT		N																				
002-0161-00 1120 HEINDL LANE		N																				
002-0162-00 1012 HEINDL LANE		N	C	N	1"	1970	C	1"	1970	SF	N	CLS	1970	Field inspection only	N	2/23/24	Cross-connection survey	Field inspection only	Y	2/23/24	Cross-connection survey	Copper/Copper
002-0163-00 1010 HEINDL LANE	P.O. BOX 342	N	C	N	1"	1970	C	1"	1970	SF	N	CLS	1970	Field inspection only	N	12/28/2023	Cross-connection survey	Field inspection only	Y	12/28/2023	Cross-connection survey	Copper/Copper
002-0164-00 1008 HEINDL LANE		N																				
002-0165-00 607 SPRUCE STREET		N																				
002-0166-00 605 SPRUCE STREET		N	C	N	1"	1970	C	1"	1970	SF	N	CLS	1970	Field inspection only	N	2/25/22	Cross-connection survey	Field inspection only	Y	2/25/22	Cross-connection survey	Copper/Copper
002-0167-00 1101 5TH STREET	P.O. BOX 12	N																				
002-0168-00 1103 5TH STREET		N																				
002-0169-00 1105 5TH STREET	P.O. BOX 383	N																				
002-0170-00 128014 SILVER FALLS TRAIL		N																				
002-0171-00 1104 5th Street	P.O. Box 94	N	C	N	1"	1970	C	1"	1970	SF	N	CLS	1970	Field inspection only	N	2/9/22	Cross-connection survey	Field inspection only	Y	2/9/22	Cross-connection survey	Copper/Copper
002-0172-00 P.O. BOX 557		N																				
002-0173-00 517 SPRUCE STREET		N																				
002-0174-00 1103 4TH STREET		N	C	N	3/4"	1970	C	3/4"	1970	SF	N	CLS	1970	Field inspection only	N	2/20/24	Cross-connection survey	Field inspection only	Y	2/20/24	Cross-connection survey	Copper/Copper
002-0175-00 1110 4th STREET		N																				
002-0176-00 1105B 4th Street		N																				
002-0176-01 1105A 4TH STREET		N																				
002-0178-00 ATTN: JILL	1424 SCHOFIELD AVENUI	N																				
002-0179-00 1107 4TH STREET		N																				
002-0180-00 1109 4TH STREET		N																				
002-0181-00 1111 4TH STREET	P.O. BOX 2	N																				
002-0182-00 1202 HEINDL LANE		N																				
002-0183-00 1200 HEINDL LANE		N	C	N	1"	1970	C	1"	1970	SF	N	CLS	1970	Field inspection only	N	11/2/22	Cross-connection survey	Field inspection only	Y	11/2/22	Cross-connection survey	Copper/Copper
002-0186-00 304 SONNENTAG LANE		N																				
002-0187-00 404 SONNENTAG LANE		N																				
002-0188-00 604 SONNENTAG LANE		N																				
002-0190-00 804 SONNENTAG LANE	P.O. BOX 173	N	C	N	1"	1990	C	1"	1990	SF	N	C	1990	Field inspection only	N	2/14/22	Cross-connection survey	Field inspection only	Y	2/14/22	Cross-connection survey	Copper/Copper
002-0194-00 1201 - 8TH STREET		N																				
002-0195-00 1003 SONNENTAG LANE	P.O. BOX 423	N	C	N	1"	1990	C	1"	1990	SF	Y	C	1990	Field inspection only	N	10/25/22	Cross-connection survey	Field inspection only	Y	10/25/22	Cross-connection survey	Copper/Copper/Pex
002-0198-00 803 SONNENTAG LANE		N																				
002-0199-00 703 SONNENTAG LANE		N	C	N	1"	1990	C	1"	1990	SF	N	C	1990	Field inspection only	N	10/17/22	Cross-connection survey	Field inspection only	Y	10/17/22	Cross-connection survey	Copper/Copper/Pex
002-0201-00 403 SONNENTAG LANE		N																				
002-0201-01 405 SONNENTAG LANE		N																				
002-0202-00 303 SONNENTAG LANE	P.O. BOX 472	N																				
002-0203-00 203 SONNENTAG LANE		N																				
002-0203-01 202 SONNENTAG LANE		N																				
002-0204-01 1203 HEINDL LANE		N																				
002-0204-02 1203 4TH STREET		N																				
002-0205-01 1205-A 4TH		N																				

002-0206-00 1301 A 4TH STREET		N																				
002-0206-01 1301-B 4TH STREET		N																				
002-0207-00 1305 4TH STREET		N																				
002-0208-00 1401-A 4TH STREET		N	C	N	1"	1970	C	1"	1970	MF	N	CLS	1970	Field inspection only	N	4/2/22	Cross-connection survey	Field inspection only	Y	4/1/22	Cross-connection survey	copper/copper
002-0208-01 1401-B 4TH ST		N	C	N		1970	C	3/4"	1970	MF	N	CLS	1970	Field inspection only	N	2/22/22	Cross-connection survey	Field inspection only	Y	2/22/22	Cross-connection survey	Copper/Copper
002-0209-00 1402 4TH STREET		N	C	N	3/4"	1970	C	3/4"	1970	SF	N	CLS	1970	Field inspection only	N	12/27/2023	Cross-connection survey	Field inspection only	Y	12/27/2023	Cross-connection survey	copper/Copper
002-0210-00 DBA MARATHON CITY MHC	1406 LAFAYETTE ST	N	C	N	1 1/2"	1970	C	1 1/2"	1970	MF	N	CLS	1970	Field inspection only	N	10/17/22	Cross-connection survey	Field inspection only	Y	10/17/22	Cross-connection survey	copper/copper
002-0210-01 DBA MARATHON CITY MHC	1406 LAFAYETTE ST	N	C	N	1 1/2"	1970	C	1 1/2"	1970	MF	N	CLS	1970	Field inspection only	N	10/17/22	Cross-connection survey	Field inspection only	Y	10/17/22	Cross-connection survey	copper/copper
002-0211-00 DBA MARATHON CITY MHC	1406 IAFAYETTE ST	N	C	N	1 1/2"	1970	C	1 1/2"	1970	MF	N	CLS	1970	Field inspection only	N	10/17/22	Cross-connection survey	Field inspection only	Y	10/17/22	Cross-connection survey	copper/copper
002-0214-00 510 WESTVIEW DRIVE		N																				
002-0215-00 516 WESTVIEW DRIVE		N																				
002-0216-00 1508 WESTVIEW DRIVE		N																				
002-0217-00 602 THORNAPPLE STREET		N																				
002-0218-00 604 THORNAPPLE		N																				
002-0218-03 904 THORNAPPLE STREET		N																				
002-0218-05 901 THORNAPPLE STREET		N																				
002-0218-06 801 THORNAPPLE STREET		N																				
002-0219-00 1004 THORNAPPLE		N																				
002-0219-01 1501 8TH STREET		N	C	N	1"	1990	C	1"	1990	SF	N	C	1990	Installed after lead ban	N	7/14/22	Cross-connection survey	Installed after lead ban	Y	7/14/22	Cross-connection survey	Copper/Copper
002-0220-00 1104 THORNAPPLE STREET		N																				
002-0224-00 1500 8TH STREET		N																				
002-0225-00 1502 8TH ST		N																				
002-0228-00 701 THORNAPPLE STREET		N	C	N	1"	1970	C	1"	1970	SF	N	CLS	1970	Field inspection only	N	12/21/2023	Cross-connection survey	Field inspection only	Y	12/21/2023	Cross-connection survey	Copper/Copper
002-0229-00 603 THORNAPPLE STREET		N																				
002-0230-00 1603 WESTVIEW DRIVE	PO BOX 544	N	C	N	3/4"	1970	C	3/4"	1970	SF	N	CLS	1970	Field inspection only	N	2/19/24	Cross-connection survey	Field inspection only	Y	2/19/24	Cross-connection survey	Copper/Copper
002-0231-00 1605 WESTVIEW DRIVE		N																				
002-0232-00 1604 WESTVIEW DRIVE		N																				
002-0233-00 1606 WESTVIEW DRIVE		N																				
002-0234-00 604 BUTTERNUT		N																				
002-0235-00 702 BUTTERNUT		N	C	N	1"	1970	P	1"	1970	SF	Y	CLS	1970	Field inspection only	N	12/13/23	Cross-connection survey	Field inspection only	Y	12/13/23	Cross-connection survey	plastic/copper
002-0246-00 603 BUTTERNUT STREET		N																				
002-0247-00 602 PHEASANT LANE		N																				
002-0248-00 1704 WESTVIEW DRIVE		N																				
002-0248-02 501 PHEASANT LN		N	C	Y	1"	2020	C	1"	2020	SF	N	C	2020	Field inspection only	Y	2020	Visual insp during install or repair	Field inspection only	Y	2020	Visual insp during install or repair	coper/coper
002-0249-00 1703 4TH STREET		N	C	N	1"	1970	C	1"	1970	SF	N	CLS	1970	Field inspection only	N	2/9/22	Cross-connection survey	Field inspection only	Y	2/9/22	Cross-connection survey	Copper/Copper
002-0250-00 1607 4TH STREET		N																				
002-0250-01 1603 4th STREET		N																				
002-0251-00 1610 4TH STREET		N																				
002-0252-00 1507 4TH STREET		N	C	N	1"	1970	C	1"	1970	SF	N	CLS	1970	Field inspection only	N	10/6/22	Cross-connection survey	Field inspection only	Y	10/6/22	Cross-connection survey	Copper/Copper
002-0253-00 517 PINE STREET	P.O. BOX 72	N																				
002-0254-00 808 5TH STREET	P.O. BOX 407	N																				
002-0255-00	517 HEMLOCK ST	N	C	N	3/4"	1935	C	3/4"	1935	SF	N	O	1935	Field inspection only	N	3/15/2023	Cross-connection survey	Field inspection only	Y	3/15/2023	Cross-connection survey	copper/pex
002-0256-00 601 HEMLOCK STREET	PO BOX 284	N																				
002-0257-00 609 HEMLOCK STREET	P.O. BOX 323	N																				
002-0258-00 608 HEMLOCK STREET		N	C	N	3/4"	1935	C	3/4"	1935	SF	N	CLS	1935	Field inspection only	N	12/8/23	Cross-connection survey	Field inspection only	Y	12/8/23	Cross-connection survey	copper/Pex
002-0259-00 709 5TH STREET	P.O. BOX 484	N	C	N	3/4"	1935	C	3/4"	1935	SF	N	O	1935	Field inspection only	N	2/6/2024	Cross-connection survey	Field inspection only	Y	2/6/2024	Cross-connection survey	Copper/Copper
002-0260-00 708 5TH STREET	P.O. BOX 352	N																				
002-0261-00 517 WALNUT STREET	P.O. BOX 392	N																				
002-0262-00 703 5TH ST		N																				
002-0263-00 609 5th ST		N																				
002-0264-00 610 5TH STREET	P.O. BOX 418	N	C	N	3/4"	1935	C	3/4"	1935	SF	N	CLS	1935	Field inspection only	N	3/8/24	Cross-connection survey	Field inspection only	Y	3/8/24	Cross-connection survey	Copper/Copper
002-0265-00 SCOTT BORCHARDT	217325 COUNTY ROAD I	N																				
002-0266-00 508 WALNUT STREET	P.O. BOX 233	N																				
002-0267-00 508 - 5TH STREET		N																				
002-0268-00 P.O. BOX 549		N																				
002-0269-00 8680 Progress Way		N																				
002-0270-00 5910 CAMP PHILLIPS ROAD		N																				
002-0271-00 601 MAIN STREET	P.O. BOX 488	N	C	N	1"	1935	C	1"	1935	NONRES	N	CLS	1935	Field inspection only	Y	12/22	Mech excav	Field inspection only	Y	12/20/23	Cross-connection survey	copper/copper
002-0272-00 RANDY WOKATSCH	142905 WHIPPOORWILL	N	C	N	3/4"	1935	C	3/4"	1935	MF	N	CLS	1935	Field inspection only	N	2/5/24	Cross-connection survey	Field inspection only	Y	2/5/24	Cross-connection survey	copper/pex-copper
002-0273-00 508 - 6TH STREET	P.O. BOX 343	N	C	N	3/4"	1935	C	3/4"	1935	SF	N	CLS	1935	Field inspection only	N	12/11/23	Cross-connection survey	Field inspection only	Y	12/11/23	Cross-connection survey	copper/copper
002-0274-00 700 MAIN STREET	P.O. BOX 214	N	C	N	3/4"	1970	C	3/4"	1970	SF	N	CLS	1970	Field inspection only	N	3/15/24	Cross-connection survey	Field inspection only	Y	3/15/24	Cross-connection survey	Copper/Copper
002-0275-00 709 MAIN STREET		N	C	N	3/4"	1970	C	3/4"	1970	SF	N	CLS	1970	Field inspection only	N	12/7/23	Cross-connection survey	Field inspection only	Y	12/7/23	Cross-connection survey	copper/copper
002-0276-00 701 MAIN STREET		N																				
002-0277-00 617 MAIN STREET		N	C	N	3/4"	1935	C	3/4"	1935	SF	N	CLS	1935	Field inspection only	N	3/1/21	Cross-connection survey	Field inspection only	Y	3/1/21	Cross-connection survey	Copper/Pex/Copper
002-0278-00 608 6TH STREET	PO BOX 514	N																				
002-0279-00 609 6TH STREET		N																				
002-0280-00 708 WALNUT STREET		N																				
002-0281-00 709 WALNUT STREET		N																				
002-0282-00 701 6th STREET	P.O. BOX 348	N																				
002-0283-00 704 6th ST		N																				
002-0284-00 616 HEMLOCK STREET	P.O. BOX 302	N																				
002-0285-00	709 6TH STREET	N																				
002-0286-00 804 6TH STREET	P.O. BOX 582	N																				
002-0287-00 PO BOX 147	801 6TH STREET	N																				
002-0288-00 P.O. BOX 628		N	C	N	3/4"	1935	C	3/4"	1935	SF	N	CLS	1935	Field inspection only	N	12/19/23	Cross-connection survey	Field inspection only	Y	12/19/23	Cross-connection survey	coppper/copper
002-0289-00 812 6TH STREET		N																				
002-0290-00 608 PINE STREET	P.O. BOX 181	N																				
002-0291-00 604 PINE STREET	P.O. BOX 633	N																				
002-0292-00 601 PINE STREET	PO BOX 13	N																				
002-0293-00 609 PINE STREET		N	C	N	3/4"	1970	C	3/4"	1970	SF	N	CLS	1970	Field inspection only	N	12/26/2023	Cross-connection survey	Field inspection only	Y	12/26/2023	Cross-connection survey	copper/Copper
002-0294-00 617 PINE STREET	P.O. BOX 396	N																				
002-0295-00 709 PINE STREET		N																				
002-0296-00 708 PINE STREET	PO Box 234	N																				
002-0298-00 808 7TH STREET		N																				
002-0299-00 809 7TH STREET		N																				
002-0300-00 801 HEMLOCK STREET		N																				
003-0301-00 800 7TH STREET	P.O. BOX 6	N																				
003-0302-00 709 HEMLOCK STREET		N	C	N	3/4"	1935	C	3/4"	1935	SF	N	CLS	1970	Field inspection only	N	12/7/23	Cross-connection survey	Field inspection only	Y	12/7/23	Cross-connection survey	copper/copper
003-0303-00 708 HEMLOCK STREET		N	C	N	3/4"	1935	C	3/4"	1970	SF	N	CLS	1970	Field inspection only	N	12/19/23	Cross-connection survey	Field inspection only	Y	12/19/23	Cross-connection survey	copper/copper
003-0304-00 207 PINE ST		N																				
003-0305-00 709 7TH STREET		N																				
003-0306-00 801 WALNUT STREET		N																				
003-0307-00 717 WALNUT STREET	P.O. BOX 281	N																				
003-0308-00 609 7TH STREET		N	C	N	3/4"	1935	C	3/4"	1935	SF	N	CLS	1935	Field inspection only	N	11/7/22	Cross-connection survey	Field inspection only	Y	11/7/22	Cross-connection survey	Copper/Copper
003-0309-00 608 7TH STREET		N																				
003-0310-00 717 MAIN STREET		N																				
003-0311-00 801 MAIN STREET	PO BOX 53	N																				
003-0312-00 809 MAIN ST		N																				

003-0313-00 817 MAIN STREET		N																				
003-0314-00 808 WALNUT STREET	P.O. BOX 548	N	C	N	1"	1935	C	1"	1935	SF	N	CLS	1935	Field inspection only	N	6/29/22	Cross-connection survey	Field inspection only	Y	6/29/22	Visual insp during install or repair	Copper/Copper
003-0315-00 817 WALNUT STREET		N	C	N	3/4"	1935	C	3/4"	1935	SF	N	CLS		Field inspection only	N	11/22/22	Cross-connection survey	Field inspection only	Y	11/22/22	Cross-connection survey	Copper/Pex
003-0316-00 705 8TH STREET		N																				
003-0317-00 708 - 8TH STREET		N																				
003-0318-00 808 HEMLOCK STREET		N																				
003-0319-00 804 8TH STREET		N																				
003-0320-00 709 8TH STREET		N	C	N	3/4"	1970	C	3/4"	1970	SF	N	CLS	1970	Field inspection only	N	3/7/24	Cross-connection survey	Field inspection only	Y	3/7/24	Cross-connection survey	copper/copper
003-0321-00 801 8TH STREET		N																				
003-0322-00 807 8TH STREET		N																				
003-0323-00 808 8TH STREET		N																				
003-0324-00 805 PINE STREET		N	C	N	3/4"	1970	C	3/4"	1970	SF	N	CLS	1970	Field inspection only	N	2/15/24	Cross-connection survey	Field inspection only	Y	2/15/24	Cross-connection survey	Copper/Copper
003-0325-00 813 PINE STREET		N																				
003-0326-00 901 8TH STREET		N	C	N	3/4"	1970	C	3/4"	1970	SF	N	CLS	1970	Field inspection only	N	2/7/24	Cross-connection survey	Field inspection only	Y	2/7/24	Cross-connection survey	Copper/Copper
003-0327-00 1001 8TH STREET		N																				
003-0328-00 910 TOWN ROAD		N	C	N	1"	1970	C	1"	1970	SF	N	CLS	1970	Field inspection only	N	9/28/22	Cross-connection survey	Field inspection only	Y	9/28/22	Cross-connection survey	Copper/Copper
003-0329-00 916 TOWN ROAD		N	C	N	1"	1970	C	1"	1970	SF	Y	CLS	1970	Field inspection only	N	10/3/22	Cross-connection survey	Field inspection only	Y	10/3/22	Cross-connection survey	Copper/Copper
003-0330-00 905 MARAVIEW DR.		N																				
003-0330-01 1005 HILLSIDE DRIVE		N																				
003-0331-00 906 MARAVIEW DRIVE		N	C	N	1"	1970	C	1"	1970	SF	N	CLS	1970	Field inspection only	N	7/13/23	Cross-connection survey	Field inspection only	Y	7/13/23	Cross-connection survey	copper/copper
003-0332-00 812 MARAVIEW DRIVE		N																				
003-0333-00 1007 HILLSIDE DRIVE		N																				
003-0334-00 1011 HILLSIDE DRIVE		N																				
003-0335-00 1013 HILLSIDE DRIVE		N	C	N	1"	1970	C	1"	1970	SF	N	CLS	1970	Field inspection only	N	10/26/22	Cross-connection survey	Field inspection only	Y	10/26/22	Cross-connection survey	Copper/Copper
003-0336-00 903 SUNSET DRIVE		N																				
003-0337-00 904 SUNSET DRIVE		N	C	N	1"	2010	C	1"	2010	SF	Y	CLS	1970	Installed after lead ban	Y	2010	Visual insp during install or repair	Installed after lead ban	Y	2010	Visual insp during install or repair	Copper/Copper
003-0338-00 1118 TOWN ROAD		N	C	N	1"	1970	C	1"	1970	SF	N	CLS	1970	Field inspection only	N	9/2/22	Cross-connection survey	Field inspection only	Y	9/2/22	Cross-connection survey	Copper/Copper
003-0339-00 906 TOWER DRIVE		N	C	N	1"	1970	C	1"	1970	SF	N	CLS	1970	Field inspection only	N	11/1/22	Cross-connection survey	Field inspection only	Y	11/1/22	Cross-connection survey	Copper/Copper
003-0340-00 905 TOWER DRIVE		N																				
003-0341-00 902 TOWER DRIVE		N																				
003-0342-00 903 TOWER DRIVE		N	C	N	1"	1970	C	1"	1970	SF	N	CLS	1970	Field inspection only	N	6/14/23	Cross-connection survey	Field inspection only	Y	6/14/23	Cross-connection survey	copper/copper
003-0343-00 1104 WALNUT STREET		N	C	N	1"	1970	C	1"	1970	SF	N	CLS	1970	Field inspection only	N	4/2/23	Cross-connection survey	Field inspection only	Y	4/2/23	Cross-connection survey	copper/Copper
003-0344-00 901 TOWER DRIVE		N																				
003-0345-00 1105 HILLSIDE DRIVE		N	C	N	1"	1970	C	1"	1970	SF	N	CLS	1970	Field inspection only	N	11/3/22	Cross-connection survey	Field inspection only	Y	11/3/22	Cross-connection survey	Copper/Copper
003-0346-00 1012 HILLSIDE DRIVE		N																				
003-0347-00 1010 HILLSIDE DRIVE		N	C	N	1"	1970	C	1"	1970	SF	N	CLS	1970	Field inspection only	N	10/27/22	Cross-connection survey	Field inspection only	Y	10/27/22	Cross-connection survey	Copper/Copper
003-0348-00 807 MARAVIEW DRIVE		N	C	N	3/4"	1970	C	3/4"	1970	SF	N	CLS	1970	Field inspection only	N	2/19/24	Cross-connection survey	Field inspection only	Y	2/19/24	Cross-connection survey	Copper/Copper
003-0349-00 810 MARAVIEW DRIVE		N																				
003-0350-00 808 MARAVIEW DRIVE		N																				
003-0351-00 805 MARAVIEW DRIVE		N																				
003-0352-00 804 MARAVIEW DRIVE		N																				
003-0353-00 803 MARAVIEW DRIVE		N																				
003-0354-00 916 WALNUT STREET		N	C	N	1"	1970	C	1"	1970	SF	Y	CLS	1970	Field inspection only	N	2/28/22	Cross-connection survey	Field inspection only	Y	2/28/22	Cross-connection survey	copper/copper
003-0355-00 1002 WALNUT STREET		N	C	N	1"	1970	C	1"	1970	SF	N	CLS	1970	Field inspection only	N	9/30/22	Cross-connection survey	Field inspection only	Y	9/30/22	Cross-connection survey	Copper/Copper
003-0356-00 1006 WALNUT STREET		N	C	N	1"	1970	C	1"	1970	SF	N	CLS	1970	Field inspection only	N	9/29/22	Cross-connection survey	Field inspection only	Y	9/29/22	Cross-connection survey	Copper/Copper
003-0357-00 1008 WALNUT STREET		N	C	N	1"	1970	C	1"	1970	SF	N	CLS	1970	Field inspection only	N	10/11/22	Cross-connection survey	Field inspection only	Y	10/11/22	Cross-connection survey	Copper/Copper
003-0358-00 1014 WALNUT STREET		N	C	N	1"	1970	C	1"	1970	SF	N	CLS	1970	Field inspection only	N	10/10/22	Cross-connection survey	Field inspection only	Y	10/10/22	Cross-connection survey	Copper/Copper
003-0359-00 1016 WALNUT STREET		N	C	N	1"	1970	C	1"	1970	SF	N	CLS	1970	Field inspection only	N	10/12/22	Cross-connection survey	Field inspection only	Y	10/12/22	Cross-connection survey	Copper/Copper
003-0360-00 1014 HILLSIDE DRIVE		N																				
003-0361-00 1013 WALNUT STREET		N																				
003-0362-00 914 WALNUT STREET		N	C	N	1"	1970	C	1"	1970	SF	N	CLS	1970	Field inspection only	N	10/27/22	Cross-connection survey	Field inspection only	Y	10/27/22	Cross-connection survey	Copper/Copper
003-0363-00 917 WALNUT STREET		N																				
003-0364-00 913 WALNUT STREET		N																				
003-0365-00 912 WALNUT STREET		N																				
003-0366-00 MCC NUMBER 10	P.O. BOX 185	N	C	N	3/4"	1970	C	3/4"	1970	NONRES	N	CLS	1970	Field inspection only	N	1/2/23	Cross-connection survey	Field inspection only	Y	1/12/23	Cross-connection survey	Copper/Copper
003-0367-00 901 MAIN STREET		N																				
003-0368-00 3759 STATE HWY 107		N	C	N	3/4"	1970	C	3/4"	1970	MF	N	CLS	1970	Field inspection only	N	3/19/24	Cross-connection survey	Field inspection only	Y	3/19/24	Cross-connection survey	Copper/Copper
003-0369-00 800 MAIN STREET		N	C	N	3/4"	1970	C	3/4"	1970	SF	N	CLS	1970	Field inspection only	N	3/18/24	Cross-connection survey	Field inspection only	Y	3/18/24	Cross-connection survey	Copper/Copper
003-0370-00 804 MAIN STREET		N																				
003-0371-00 808 MAIN STREET		N	C	N	3/4"	1970	C	3/4"	1970	SF	N	CLS	1970	Field inspection only	N	2/9/24	Cross-connection survey	Field inspection only	Y	2/9/24	Cross-connection survey	Copper/Copper
003-0372-00 816 MAIN STREET	PO BOX 324	N	C	N	3/4"	1970	C	3/4"	1970	SF	Y	CLS	1970	Field inspection only	N	3/22/24	Cross-connection survey	Field inspection only	Y	3/22/24	Cross-connection survey	Copper/Copper
003-0373-00 609 - 8TH STREET		N	C	N	3/4"	1970	C	3/4"	1970	SF	N	CLS	1970	Field inspection only	N	12/27/2023	Cross-connection survey	Field inspection only	Y	12/27/23	Cross-connection survey	Copper/Copper
003-0374-00 1200 STATE HWY 107		N																				
003-0375-00 1300 STHY 107 SOUTH	P.O. BOX 456	N																				
003-0375-01 910 MAIN STREET		N	C	N	1"	1970	C	3/4"	1970	SF	N	CLS	1970	Field inspection only	N	2/21/22	Cross-connection survey	Field inspection only	Y	2/21/22	Cross-connection survey	Copper/Copper
003-0376-00 908 MAIN STREET		N																				
003-0377-00 901 COUNTY RD B		N																				
003-0378-00 909 CTH B		N																				
003-0379-00 917 CTH B		N																				
003-0380-00 919 CTH B	P.O. BOX 83	N	C	N	1"	1970	C	1"	1970	SF	N	CLS	1970	Field inspection only	N	3/29/22	Cross-connection survey	Field inspection only	Y	3/29/22	Cross-connection survey	Copper/Copper
003-0380-01 1000 MAIN STREET		N	C	N	1"	1970	P	1"	1970	SF	Y	CLS	1970	Field inspection only	N	2/21/22	Cross-connection survey	Field inspection only	Y	2/21/22	Cross-connection survey	plastic/copper
003-0381-00 1201 COUNTY ROAD B		N	C	N	1"	1970	C	1"	1970	SF	N	CLS	1970	Field inspection only	N	3/5/24	Cross-connection survey	Field inspection only	Y	3/5/24	Cross-connection survey	Well not connected to city water lines
003-0382-00 1205 CTH B		N																				
003-0382-01 1207 CTH B		N																				
003-0384-00 1210 CTH B		N	C	N	1"	2000	C	1"	2000	SF	N	C	2000	Installed after lead ban	Y	12/20/23	Cross-connection survey	Field inspection only	Y	12/20/23	Cross-connection survey	Copper/Copper
003-0385-00 1109 WASHINGTON		N																				
003-0386-00 312 SOUTH ROAD		N																				
003-0387-00 306 SOUTH ROAD		N																				
003-0388-00 202 SOUTH ROAD		N	C	N	1"	2000	C	1"	2000	SF	N	C	2000	Installed after lead ban	Y	12/5/23	Cross-connection survey	Field inspection only	Y	12/5/23	Cross-connection survey	Copper/Copper
003-0389-00 110 SOUTH ROAD		N	C	N	1"	2000	C	1"	2000	SF	N	C	2000	Installed after lead ban	N	2/24/22	Cross-connection survey	Field inspection only	Y	2/24/22	Cross-connection survey	Copper/Copper
003-0390-00 210 SOUTH ROAD		N																				
003-0390-01 1206 COUNTY HWY B		N	C	N	1"	1970	C	1"	1970	SF	N	CLS	1970	Field inspection only	N	2/18/22	Cross-connection survey	Field inspection only	Y	2/18/22	Cross-connection survey	Copper/Copper
003-0391-00 1202 CTH B		N	C	N	1"	1970	C	1"	1970	SF	N	CLS	1970	Field inspection only	N	2/8/22	Cross-connection survey	Field inspection only	Y	2/8/22	Cross-connection survey	Copper/Copper
003-0392-00 1010 COUNTY ROAD B		N																				
003-0393-00 1008 COUNTY HWY B		N																				
003-0394-00 924 COUNTY ROAD B		N																				
003-0395-00 922 COUNTY ROAD B		N	C	N	3/4"	1970	P	3/4"	1970	SF	N	CLS	1970	Field inspection only	N	3/12/24	Cross-connection survey	Field inspection only	Y	3/12/24	Cross-connection survey	Copper/Copper
003-0396-00 920 CTH B		N																				
003-0397-00 916 COUNTY HWY B		N																				
003-0398-00 900 CTH B		N	C	N	3/4"	1970	C	3/4"	1970	SF	N	CLS	1970	Field inspection only	N	2/28/24	Cross-connection survey	Field inspection only	Y	2/28/24	Cross-connection survey	Copper/Copper
003-0399-00 816 MARKET STREET		N	C	N	3/4"	1970	C	3/4"	1970	SF	N	CLS	1970	Field inspection only	N	2/16/24	Cross-connection survey	Field inspection only	Y	2/16/24	Cross-connection survey	Copper/Copper
003-0400-00 817 MARKET STREET		N																				
003-0401-00 809 MARKET STREET	138555 FOUR MILE ROAI	N	C	N	3/4"	1970	C	3/4"	1970	SF	N	CLS	1970	Field inspection only	N	2/14/24	Cross-connection survey	Field inspection only	Y	2/14/24	Cross-connection survey	Copper/Copper
003-0402-00 801 MARKET STREET		N	C	N	3/4"	1970	C	3/4"	1970	SF	N	CLS	1970	Field inspection only	N	12/12/23	Cross-connection survey	Field inspection only	Y	12/12/23	Cross-connection survey	Copper/Copper
003-0403-00 716 MARKET STREET	P.O. BOX 102	N																				
003-0404-00 313 8TH STREET		N																				
003-0405-00 308 9TH STREET		N																				
003-0406-00 911 WASHINGTON STREET		N																				

003-0407-00 311 9TH STREET	P.O. BOX 486	N																				
003-0408-00 1006 WASHINGTON STREET		N																				
003-0409-00 1008 WASHINGTON STREET		N																				
003-0410-00 1010 WASHINGTON STREET		N																				
003-0411-00 1009 WASHINGTON STREET		N	C	N	1"	1970	C	1"	1970	SF	N	CLS	1970	Field inspection only	N	3/11/22	Cross-connection survey	Field inspection only	Y	3/11/22	Cross-connection survey	copper/copper
003-0412-00 1102 WASHINGTON STREET		N																				
003-0413-00 1108 WASHINGTON STREET		N																				
003-0414-00 1107 WASHINGTON STREET		N																				
003-0415-00 309 8TH STREET		N																				
003-0416-00 305 8TH STREET		N																				
003-0417-00 909 HICKORY STREET		N																				
003-0418-00 1001 HICKORY		N	C	N	3/4"	1970	C	3/4"	1970	SF	N	CLS	1970	Field inspection only	N	5/11/22	Cross-connection survey	Field inspection only	Y	5/11/22	Cross-connection survey	copper/copper
003-0419-00 1003 HICKORY STREET		N	C	N	1"	1970	C	1"	1970	SF	N	CLS	1970	Field inspection only	N	3/4/22	Cross-connection survey	Field inspection only	Y	3/4/22	Cross-connection survey	Copper/Copper
003-0420-00 1005 HICKORY STREET		N																				
003-0421-00 1007 HICKORY STREET		N	C	N	1"	1970	C	1"	1970	SF	N	CLS	1970	Field inspection only	N	3/1/22	Cross-connection survey	Water sampling only	Y	3/1/22	Cross-connection survey	Copper/Copper
003-0422-00 1009 HICKORY STREET		N																				
003-0423-00 209 10TH STREET		N	C	N	1"	2000	C	1"	2000	SF	Y	C	2000	Field inspection only	N	2/23/24	Cross-connection survey	Field inspection only	Y	2/23/24	Cross-connection survey	Copper/Copper
003-0424-00 301 10TH STREET		N																				
003-0424-01 1107 HICKORY STREET		N																				
003-0425-00 1010 HICKORY STREET		N																				
003-0426-00 1006 HICKORY STREET		N																				
003-0427-00 1004 HICKORY STREET		N																				
003-0428-00 1002 HICKORY STREET		N	C	N	3/4"	1970	C	3/4"	1970	SF	N	CLS	1970	Field inspection only	N	12/4/2023	Cross-connection survey	Field inspection only	Y	12/4/2023	Cross-connection survey	Copper/Copper
003-0429-00 910 HICKORY STREET		N																				
003-0430-00 908 HICKORY STREET		N																				
003-0431-00 209 - 8TH STREET		N	C	N	3/4"	1970	C	3/4"	1970	SF	N	CLS	1970	Field inspection only	N	2/25/22	Cross-connection survey	Field inspection only	Y	2/25/22	Cross-connection survey	Copper/Copper
003-0431-01 200 8TH STREET	BOX 567	N	C	N	3/4"	1970	C	3/4"	1970	SF	N	CLS	1970	Field inspection only	N	4/1/22	Cross-connection survey	Field inspection only	Y	4/1/22	Cross-connection survey	Copper/Copper/Pex
003-0432-00 208 8TH STREET		N																				
003-0433-00 205 8TH STREET		N	C	N	3/4"	1970	C	3/4"	1970	SF	N	CLS	1970	Field inspection only	N	12/21/23	Cross-connection survey	Field inspection only	Y	12/21/23	Cross-connection survey	Copper/Copper
003-0434-00 909 CHESTNUT STREET		N	C	N	3/4"	1970	C	3/4"	1970	SF	N	CLS	1970	Field inspection only	N	12/26/23	Cross-connection survey	Field inspection only	Y	12/26/23	Cross-connection survey	copper/copper
003-0435-00 1001 CHESTNUT STREET		N																				
003-0436-00 1005 CHESTNUT STREET		N																				
003-0437-00 1009 CHESTNUT STREET		N	C	N	1"	2000	C	1"	2000	SF	Y	C	2000	Installed after lead ban	N	2/18/22	Cross-connection survey	Field inspection only	Y	2/18/22	Cross-connection survey	Copper/Copper
003-0438-00 201 10TH STREET	P.O. BOX 5	N																				
003-0439-00 105 10TH STREET		N																				
003-0439-01 1010 CHESTNUT STREET		N	C	N	1 1/4"	2000	C	1 1/4"	2000	SF	N	C	2000	Installed after lead ban	N	11/14/22	Cross-connection survey	Field inspection only	Y	11/14/22	Cross-connection survey	Copper/Copper
003-0440-00 1008 CHESTNUT STREET		N																				
003-0441-00 1006 CHESTNUT STREET		N																				
003-0441-01 1004 CHESTNUT STREET		N																				
003-0442-00 1002 CHESTNUT STREET		N																				
003-0443-00 912 CHESTNUT STREET		N																				
003-0444-00 906 CHESTNUT STREET	P.O. BOX 293	N	C	N	3/4"	1970	C	3/4"	1970	SF	N	CLS	1970	Field inspection only	N	2/15/22	Cross-connection survey	Field inspection only	Y	2/15/22	Cross-connection survey	Copper/Copper
003-0445-00 109 8TH STREET		N	C	N	3/4"	1970	C	3/4"	1970	SF	N	CLS	1970	Field inspection only	N	2/12/24	Cross-connection survey	Field inspection only	Y	2/12/24	Cross-connection survey	Copper/Copper
003-0446-00 804 CHESTNUT STREET	P.O. BOX 174	N	C	N	3/4"	1970	C	3/4"	1970	SF	N	CLS	1970	Field inspection only	N	3/9/22	Cross-connection survey	Field inspection only	Y	3/9/22	Cross-connection survey	Copper/Copper
003-0447-00 108 8TH STREET		N																				
003-0448-00 105 8TH STREET		N																				
003-0449-00 104 8TH STREET	P.O. BOX 391	N																				
003-0450-00 900 EAST STREET	P.O. BOX 100	N																				
004-0451-00 909 EAST STREET		N																				
004-0452-00 1001 EAST STREET	P.O. BOX 96	N	C	N	1"	1970	C	1"	1970	SF	N	CLS	1970	Field inspection only	N	4/4/22	Cross-connection survey	Field inspection only	Y	4/4/22	Cross-connection survey	Copper/Copper
004-0453-00 1003 EAST STREET	P.O. BOX 187	N																				
004-0454-00 1007 EAST STREET		N	C	N	1"	2000	C	3/4"	2000	SF	N	C	2000	Installed after lead ban	N	2/23/22	Cross-connection survey	Field inspection only	Y	2/23/22	Cross-connection survey	Copper/Copper
004-0455-00 1009 EAST STREET		N	C	N	1"	2000	C	1"	2000	SF	N	C	2000	Installed after lead ban	N	2/23/22	Cross-connection survey	Field inspection only	Y	2/23/22	Cross-connection survey	Copper/Copper
004-0455-01 1008 EAST STREET		N	C	N	1"	2000	C	1"	2000	SF	N	C	2000	Installed after lead ban	N	10/31/22	Cross-connection survey	Field inspection only	Y	10/31/22	Cross-connection survey	Copper/Pex
004-0456-00 1101 EAST STREET		N	C	N	1"	2000	C	1"	2000	SF	N	C	2000	Installed after lead ban	N	2/15/22	Cross-connection survey	Field inspection only	Y	2/15/22	Cross-connection survey	Copper/Copper
004-0456-01 102 10TH STREET		N	C	N	1"	2000	C	1"	2000	SF	N	C	2000	Installed after lead ban	N	2/17/22	Cross-connection survey	Field inspection only	Y	2/17/22	Cross-connection survey	copper/copper
004-0457-00 1103 EAST STREET		N	C	N	1"	2000	C	1"	2000	SF	N	C	2000	Installed after lead ban	N	6/7/22	Cross-connection survey	Field inspection only	Y	6/7/22	Cross-connection survey	Copper/Copper
004-0458-00 1105 EAST STREET		N																				
004-0458-01	1104 EAST STREET	N																				
004-0459-00 1004 EAST STREET		N																				
004-0460-00 1002 EAST STREET		N	C	N	1 1/4"	2000	C	1 1/4"	2000	SF	N	C	2000	Installed after lead ban	N	11/2/22	Cross-connection survey	Field inspection only	Y	11/2/22	Cross-connection survey	Copper/Copper
004-0461-00 806 EAST STREET	P.O. BOX 183	N	C	N	1"	1970	C	1"	1970	SF	N	CLS	1970	Field inspection only	N	10/31/22	Cross-connection survey	Field inspection only	Y	10/31/22	Cross-connection survey	Copper/Copper
004-0462-00 809 EAST STREET	17238 EAST CIRCLE DRI	N	C	N	3/4"	1970	C	3/4"	1970	SF	N	CLS	1970	Field inspection only	N	2/28/24	Cross-connection survey	Field inspection only	Y	2/28/24	Cross-connection survey	Copper/Copper
004-0463-00 PO BOX 561	801 EAST STREET	N																				
004-0464-00 C/O STEVE MENZNER	P.O. BOX 1393	N																				
004-0465-00 716 EAST STREET	P.O. BOX 1	N																				
004-0466-00 708 EAST STREET		N																				
004-0467-00 717 EAST STREET		N																				
004-0468-00 716 CHESTNUT STREET		N																				
004-0469-00 713 CHESTNUT STREET		N																				
004-0470-00 800 CHESTNUT STREET		N																				
004-0471-00 801 CHESTNUT STREET		N	C	N	3/4"	1935	C	3/4"	1935	SF	N	CLS	1935	Field inspection only	N	2/19/24	Cross-connection survey	Field inspection only	Y	2/19/24	Cross-connection survey	Copper/Copper
004-0472-00 800 HICKORY STREET	P.O. BOX 148	N																				
004-0473-00 716 HICKORY STREET		N																				
004-0474-00 708 HICKORY STREET		N	C	N	1"	1970	C	1"	1970	SF	N	CLS	1970	Field inspection only	N	12/28/23	Cross-connection survey	Field inspection only	Y	12/28/23	Cross-connection survey	copper/copper
004-0475-00 709 Hickory St		N																				
004-0476-00 304 7TH STREET		N	C	N	3/4"	1960	C	3/4"	1960	SF	N	CLS	1960	Field inspection only	N	2/13/24	Cross-connection survey	Field inspection only	Y	2/13/24	Cross-connection survey	copper/copper
004-0477-00 716 WASHINGTON STREET		N																				
004-0478-00 225077 Rib Mountain Drive		N																				
004-0479-00 712 MARKET STREET	P.O. BOX 7	N	C	N	2"	1960	C	2"	1960	SCH/DC	N	CLS	1960	Diameter > 2 inches	N	3/6/24	Cross-connection survey	Field inspection only	Y	3/6/24	Cross-connection survey	copper/copper
004-0480-00 719 Market Street		N																				
004-0481-00 713 MARKET STREET		N																				
004-0483-00 701 MARKET STREET	P.O. BOX 54	N	C	N	1"	1970	C	1"	1970	SF	N	CLS	1970	Field inspection only	N	2/1/2024	Cross-connection survey	Field inspection only	Y	2/1/2024	Cross-connection survey	Copper/Copper
004-0484-00 617 MARKET STREET	P.O. BOX 393	N																				
004-0485-00 608 MARKET STREET	P.O. BOX 224	N	C	N	3/4"	1935	C	3/4"	1935	SF	N	CLS	1935	Field inspection only	N	2/2/2024	Cross-connection survey	Field inspection only	Y	2/2/2024	Cross-connection survey	Copper/Copper
004-0486-00 616 MARKET STREET	P.O. BOX 111	N																				
004-0487-00 404 6TH STREET	P.O. BOX 642	N	C	N	3/4"	1935	C	3/4"	1935	SF	N	CLS	1935	Field inspection only	N	3/8/24	Cross-connection survey	Field inspection only	Y	3/8/24	Cross-connection survey	Copper/Copper
004-0488-00 616 WASHINGTON STREET	P.O. BOX 81	N																				
004-0489-00 703 HICKORY STREET		N																				
004-0490-00 617 HICKORY STREET		N																				
004-0491-00 608 HICKORY STREET		N	C	N	3/4"	1935	C	3/4"	1935	SF	N	CLS	1935	Field inspection only	N	10/9/24	Cross-connection survey	Field inspection only	Y	10/9/24	Cross-connection survey	Copper/Copper
004-0492-00 208 6TH STREET		N	C	N	3/4"	1935	C	3/4"	1935	SF	N	CLS	1935	Field inspection only	N	2/9/24	Cross-connection survey	Field inspection only	Y	2/9/24	Cross-connection survey	Copper/Copper
004-0494-00 700 HICKORY STREET		N	C	N	3/4"	1970	C	3/4"	1970	SF	N	CLS	1970	Field inspection only	N	1/31/24	Cross-connection survey	Field inspection only	Y	1/31/24	Cross-connection survey	Copper/Copper
004-0495-00 202 6TH STREET		N																				
004-0496-00 201 - 6TH STREET		N																				
004-0497-00 700 CHESTNUT STREET		N																				
004-0498-00 616 CHESTNUT STREET	P.O. BOX 384	N																				
004-0499-00 101 6TH STREET		N																				

004-0500-00 709 EAST STREET		N																				
004-0501-00 700 EAST STREET		N																				
004-0502-00 610 EAST STREET		N	C	N	1 1/4"	1935	C	1 1/4"	1935	SF	N	CLS	1935	Field inspection only	N	2/14/24	Cross-connection survey	Field inspection only	Y	2/14/24	Cross-connection survey	Copper/Copper
004-0503-00 613 EAST STREET		N																				
004-0504-00 611 EAST STREET		N																				
004-0505-00 600 EAST STREET	P.O. BOX 114	N																				
004-0506-00 611 SPRING VALLEY COURT		N																				
004-0507-00 615 SPRING VALLEY COURT	P.O. BOX 387	N	C	N	1"	1970	C	1"	1970	SF	N	CLS	1970	Field inspection only	N	2/7/24	Cross-connection survey	Field inspection only	Y	2/7/24	Cross-connection survey	Copper/Copper
004-0508-00 619 SPRING VALLEY COURT		N	C	N	1"	1970	C	3/4"	1970	SF	N	CLS	1970	Field inspection only	N	2/10/22	Cross-connection survey	Field inspection only	Y	2/10/22	Cross-connection survey	Copper/Copper
004-0509-00 610 CHESTNUT STREET		N																				
004-0510-00 604 CHESTNUT STREET	PO BOX 204	N																				
004-0511-00 600 CHESTNUT STREET		N	C	N	3/4"	1935	C	3/4"	1935	SF	N	CLS	1935	Field inspection only	N	3/5/24	Cross-connection survey	Field inspection only	Y	3/5/24	Cross-connection survey	Copper/Copper
004-0512-00 203 5TH STREET		N	C	N	3/4"	1935	P	3/4"	1935	SF	N	CLS	2020	Field inspection only	N	10/11/24	Cross-connection survey	Field inspection only	Y	10/11/24	Cross-connection survey	Copper/Pex
004-0513-00 516 CHESTNUT STREET		N																				
004-0514-00 509 CHESTNUT STREET		N	C	N	3/4"	1935	C	3/4"	1935	SF	N	CLS	1935	Field inspection only	N	4/30/24	Cross-connection survey	Field inspection only	Y	4/30/24	Cross-connection survey	Copper/Copper
004-0515-00 517 CHESTNUT STREET		N																				
004-0516-00 516 HICKORY STREET		N	C	N	3/4"	1935	C	3/4"	1935	SF	N	CLS	1935	Field inspection only	N	12/20/2024	Cross-connection survey	Field inspection only	Y	12/20/2023	Cross-connection survey	copper/copper
004-0517-00 517 HICKORY STREET		N																				
004-0518-00 600 HICKORY STREET		N	C	N	3/4"	1935	C	3/4"	1935	SF	N	CLS	1935	Field inspection only	N	10/14/24	Cross-connection survey	Field inspection only	Y	10/14/24	Cross-connection survey	copper/copper
004-0519-00 601 HICKORY STREET		Y	C	N	3/4"	1935	L	3/4"	1935	SF	N	CLS	1935	Field inspection only	N	10/11/24	Cross-connection survey	Field inspection only	Y	10/11/24	Cross-connection survey	lead/copper
004-0520-00 E7816 Seefeld Rd.		N																				
004-0521-00 516 WASHINGTON STREET		N	C	N	3/4"	1935	C	3/4"	1935	SF	N	CLS	1935	Field inspection only	N	10/11/24	Cross-connection survey	Field inspection only	Y	10/11/24	Cross-connection survey	Copper/Copper
004-0522-00 405 - 5TH STREET	PO BOX 315	N	C	N	3/4"	1935	C	3/4"	1935	SF	N	CLS	1935	Field inspection only	N	3/22/24	Cross-connection survey	Field inspection only	Y	3/22/24	Cross-connection survey	Copper/Copper
004-0523-00 409 5TH STREET		N	C	N	3/4"	1935	P	3/4"	1935	SF	N	CLS	1935	Field inspection only	N	3/15/24	Cross-connection survey	Field inspection only	Y	3/15/24	Cross-connection survey	Copper/Pex
004-0524-00 505 5TH STREET	P.O. BOX 543	N	C	N	3/4"	1935	P	3/4"	1935	SF	N	CLS	1935	Field inspection only	N	2/6/24	Cross-connection survey	Field inspection only	Y	2/6/24	Cross-connection survey	Copper/Plastic Galv. Copper
004-0525-00 PO BOX 317		N																				
004-0525-01 PO BOX 317		N																				
004-0526-00 511 MARKET STREET		N	C	N	3/4"	1935	C	3/4"	1935	SF	N	CLS	1935	Field inspection only	N	12/4/23	Cross-connection survey	Field inspection only	Y	12/4/23	Cross-connection survey	copper/copper
004-0527-00 503 4TH ST		N																				
004-0528-00 401 4TH STREET	P.O. BOX 441	N																				
004-0529-00 401 4TH STREET	P.O. BOX 441	N																				
004-0529-01	P.O. BOX 487	N	C	N	2"	2010	P	2"	2010	NONRES	N	C	2010	Field inspection only	Y	2010	Visual insp during install or repair	Field inspection only	Y	1/10/24	Cross-connection survey	plastic/copper
004-0529-02	P.O. BOX 487	N	C	N	2"	2010	P	2"	2010	NONRES	N	C	2010	Field inspection only	Y	2010	Visual insp during install or repair	Field inspection only	Y	1/10/24	Cross-connection survey	plastic/copper
004-0530-00 508 WASHINGTON STREET		N																				
004-0531-00 504 WASHINGTON STREET		N	C	N	3/4"	1935	C	3/4"	1935	SF	N	C	1935	Field inspection only	N	1935	Cross-connection survey	Field inspection only	Y	10/14/24	Cross-connection survey	coppper/copper
004-0533-00 209 4TH STREET		N																				
004-0534-00 203 4TH STREET		N																				
004-0535-00 109 4TH STREET		N																				
004-0536-00 107 4th ST		N	C	N	3/4"	1970	C	3/4"	1970	SF	N	O	1970	Field inspection only	N	12/11/23	Cross-connection survey	Field inspection only	Y	12/11/23	Cross-connection survey	copper/Pex
004-0537-00 517 EAST STREET		N																				
004-0538-00 105 E. 4TH STREET		N																				
004-0539-00 103 E. 4TH STREET		N																				
004-0540-00 100 SPRING VALLEY DRIVE	P.O. BOX 37	N																				
004-0541-00 300 EAST 4TH STREET		N																				
004-0541-01 300 COUNTY RD NN		N	DI	N	6"	2020	DI	4"	2020	SCH/DC	Y	O	2020	Installed after lead ban	Y	2020	Visual insp during install or repair	Installed after lead ban	Y	2020	Visual insp during install or repair	di/copper
004-0543-01 308 4th St		N	C	N	2"	1935	P	2"	1335	NONRES	N	CLS	1935	Diameter > 2 inches	N	3/6/24	Cross-connection survey	Diameter > 2 inches	Y	3/6/24	Cross-connection survey	plastic/copper
004-0544-00 C/O WISCONSIN MANAGEMENT CO	PO BOX 209352	N																				
004-0545-02	PO BOX 487	N	DI	N	8"	2010	DI	8"	2010	NONRES	N	C	2010	Installed after lead ban	Y	1/10/24	Cross-connection survey	Installed after lead ban	Y	1/10/24	Cross-connection survey	ductal/copper
004-0545-03	PO BOX 487	N	DI	N	8"	2010	DI	8"	2010	NONRES	N	C	2010	Installed after lead ban	Y	1/10/24	Cross-connection survey	Installed after lead ban	Y	1/10/24	Cross-connection survey	ductal/copper
004-0547-00 318 MARKET STREET		N	C	N	3/4"	1935	C	3/4"	1935	SF	Y	CLS	1935	Field inspection only	N	2/16/24	Cross-connection survey	Field inspection only	Y	2/16/24	Cross-connection survey	Copper/Copper
004-0548-00 310 MARKET STREET	P.O. BOX 217	N																				
004-0549-00 301 Market Street		N	C	N	3/4"	1935	C	3/4"	1935	SF	N	CLS	1935	Field inspection only	N	4/8/24	Cross-connection survey	Field inspection only	Y	4/8/24	Cross-connection survey	Copper/Copper
004-0551-00 300 MARKET STREET	PO BOX 103	N	C	N	1"		P	1"		SF	N	O		Field inspection only	N	4/8/24	Cross-connection survey	Field inspection only	Y	4/8/24	Cross-connection survey	Pex/Galvanized /Copper
004-0553-00 3759 HWY. 107 SOUTH		N	C	N	3/4"	1935	C	3/4"	1935	SF	N	CLS	1935	Field inspection only	N	2/29/24	Cross-connection survey	Field inspection only	Y	2/29/24	Cross-connection survey	copper/copper
004-0554-00 400 2ND STREET	PO BOX 490	N																				
004-0555-00 403 2ND STREET	P.O. BOX 133	N	C	N	3/4"	1935	C	3/4"	1935	SF	N	CLS	1935	Field inspection only	N	2/5/2024	Cross-connection survey	Field inspection only	Y	2/5/2024	Cross-connection survey	Copper/Copper
004-0556-00 311 WASHINGTON STREET	P.O. BOX 331	N																				
004-0557-00 310 WASHINGTON STREET	P.O. BOX 112	N	C	N	3/4"	1970	C	3/4"	1970	SF	N	CLS	1970	Field inspection only	N	12/26/23	Cross-connection survey	Field inspection only	Y	12/26/23	Cross-connection survey	copper/copper
004-0558-00 304 WASHINGTON STREET	P.O. BOX 558	N																				
004-0559-00 207 WASHINGTON STREET	PO BOX 353	N																				
004-0561-00	308 2ND STREET	N																				
004-0562-00 304 - 2ND STREET		N																				
004-0563-00 300 2ND STREET		N	C	N	3/4"	1935	C	3/4"	1935	SF	N	CLS	1935	Field inspection only	N	1/31/24	Cross-connection survey	Field inspection only	Y	1/31/24	Cross-connection survey	copper/copper
004-0564-00 303 2ND STREET	P.O. BOX 345	N																				
004-0565-00 311 HICKORY STREET	P.O. Box 481	N																				
004-0566-00 123018 SCHNAPPSVILLE RD		N																				
004-0567-00 209 2ND STREET	P.O. BOX 74	N	C	N	3/4"	1970	C	3/4"	1970	SF	Y	CLS	1970	Field inspection only	N	6/27/22	Cross-connection survey	Field inspection only	Y	6/27/22	Cross-connection survey	Copper/Copper
004-0568-00 210 2ND STREET	P.O. BOX 313	N																				
004-0569-00 203 2ND STREET		N																				
004-0570-00 200 3RD STREET	P.O. BOX 271	N																				
004-0570-01 300 3RD STREET	PO BOX 502	N																				
004-0571-00 211 CHESTNUT STREET		N																				
004-0572-00 208 CHESTNUT STREET		N																				
004-0573-00 212 CHESTNUT STREET		N																				
004-0574-00 PO BOX 37		N																				
004-0576-00 MCC #4	P.O. BOX 185	N																				
004-0578-01 P.O. BOX 185		N																				
004-0580-00 MCC #3	P.O. BOX 185	N																				
004-0581-00 204 EAST STREET	P.O. BOX 37	N																				
004-0585-00 205 NORTH STREET	P.O. BOX 100	N																				
004-0586-00 205 NORTH STREET	P.O. BOX 100	N																				
004-0587-00 106 CHESTNUT STREET	P.O. BOX 487	N																				
004-0588-00 104 CHESTNUT STREET	P.O. BOX 487	N																				
004-0588-01 104 CHESTNUT ST		N	DI	N	6"	2023	DI	6"	2023	NONRES	N	C	2023	Field inspection only	Y	2/29/24	Visual insp during install or repair	Field inspection only	Y	2/29/24	Visual insp during install or repair	ductal/copper
004-0589-00 205 NORTH STREET	P.O. BOX 100	N																				
004-0589-01 205 NORTH STREET	P.O. BOX 100	N																				
004-0589-02 205 NORTH STREET	P.O. BOX 100	N																				
004-0589-03 205 NORTH STREET	PO BOX 100	N																				
004-0590-00 203 FIRST STREET		N																				
004-0593-00 208 HICKORY STREET		N																				
004-0594-00 205 HICKORY STREET		N																				
004-0597-00 307 1ST STREET		N	C	N	3/4"	1935	C	3/4"	1935	SF	N	CLS	1935	Field inspection only	N	1/25/24	Cross-connection survey	Field inspection only	Y	1/25/24	Cross-connection survey	Copper/Copper
004-0598-00 311 1ST STREET		N																				
004-0604-00 405 1ST STREET	P.O. BOX 621	N	C	N	3/4"	1935	C	3/4"	1935	SF	N	CLS	1935	Field inspection only	N	3/19/24	Cross-connection survey	Field inspection only	Y	3/19/24	Cross-connection survey	Copper/Copper
004-0605-01 P.O. BOX 217		N																				
004-0607-00 102 SOUTH ROAD		N	C	N	1"	2000	P	1"	2000	SF	N	C	2000	Field inspection only	N	2/24/22	Cross-connection survey	Field inspection only	Y	2/24/22	Cross-connection survey	plastic/copper
004-0608-00 98 SOUTH ROAD		N																				
004-0609-00 94 SOUTH ROAD		N	P	N	1 1/4"	2000	P	1 1/4"	2000	SF	N	C	2000	Installed after lead ban	N	2/17/22	Cross-connection survey	Field inspection only	Y	2/17/22	Cross-connection survey	Pex/Pex

004-0610-00	90 SOUTH ROAD		N																			
004-0611-00	86 SOUTH ROAD		N	P	N	1"	2000	P	1"	2000	SF	N	O	2000	Installed after lead ban	N	3/3/22	Cross-connection survey	Field inspection only	Y	3/3/22	Cross-connection survey	plastic/pex
004-0612-00	82 SOUTH ROAD		N	P	N	1"	2000	P	1"	2000	SF	Y	C	2000	Installed after lead ban	N	2/11/22	Cross-connection survey	Field inspection only	Y	2/11/22	Cross-connection survey	Pex/Copper/Pex
004-0613-00	78 SOUTH ROAD		N																			
004-0614-00	74 SOUTH ROAD		N																			
004-0615-00	70 SOUTH ROAD		N																			
004-0617-00	1108 VITELLO LANE		N																			
004-0619-00	1100 VITELLO LANE		N																			
004-0629-00	101 10TH STREET		N	P	N	1"	2000	P	1"	2000	SF	N	O	2000	Installed after lead ban	N	2/28/22	Visual insp during install or repair	Field inspection only	Y	2/28/22	Cross-connection survey	Pex/Pex
005-0700-00	5512 STATE RD 19 AND 113		N																			
005-0712-00	4910 N Co Rd 900 E		N																			
005-0717-00	6996 PIAZZA GRANDE AVE 309		N																			
005-0733-00	Division of River Country Coop	PO Box 250	N																			
006-0001-00	100 MAIN STREET	P.O. BOX 217	N	C																		
006-0001-01	409 NORTH STREET		N																			
006-0002-00	100 MAIN STREET	P.O. BOX 217	N	DI	N	8"	2023	P	8"	2/29/2024	NONRES	N	C	2023	Installation record	Y	2023	Customer self id	Installed after lead ban	Y	2/29/24	Visual insp during install or repair	8' PVC/copper
006-0003-00	MCC #7	P.O. BOX 185	N																			
006-0003-01	304 EAST STREET	PO BOX 185	N																			
006-0003-03	304 EAST STREET	PO BOX 185	N																			
006-0004-00	NEW WAREHOUSE - 1ST/MARKET S	P.O. BOX 217	N																			
006-0005-00	304 EAST STREET	P.O. BOX 185	N																			
006-0006-00	550 MARATECH AVENUE		N																			
006-0007-00	PO BOX 217		N																			
006-0007-01	PO BOX 217		N																			
006-0008-00	204 EAST STREET	PO BOX 37	N																			
006-0009-00	498 MARATECH AVENUE		N																			
006-0010-00		PO BOX 487	N																			
006-0011-00	P.O. BOX 185	304 EAST STREET	N																			
006-0012-00	530 MARATECH AVENUE		N																			
006-0013-00	580 MARATECH AVE		N																			
006-0014-00	BLUE STONE ESTATES SOUTH	401 RANGER STREET	N																			
006-0015-00	BLUE STONE ESTATES NORTH	401 RANGER STREET	N																			
006-0017-00	497 MARATECH AVENUE		N																			
006-0018-00	983 154TH AVE		N																			
006-0019-00	960 BLUE STONE LN		N																			
006-0020-00	962 BLUE STONE LN		N																			
008-0010-00	1005 NORTH 28TH AVENUE		N																			
008-0011-00	945 RIVER ROAD		N																			
008-0020-00	P.O. BOX 185	900 WEISENBERGER ROA	N	DI	N	6"	2000	C	2"	2000	NONRES	N	C	2000	Installed after lead ban	Y	2000	Visual insp during install or repair	Installed after lead ban	Y	1/19/24	Cross-connection survey	copper/copper
008-0030-00	P.O. BOX 100		N																			
008-0031-00	1010 KRAUTKRAMER ROAD		N																			
008-0500-00	640 NORTH RIDGE ROAD		N																			
009-0010-00	PO BOX 28		N																			
009-0020-00	PO BOX 28		N	DI	N	6"	2000	C	2"	2000	NONRES	N	C	2000	Installed after lead ban	N	1/25/23	Cross-connection survey	Field inspection only	Y	1/25/23	Cross-connection survey	duct/copper
009-0030-00	771 GRAND AVENUE		N	DI	N	6"	2000	C	1 1/4"	2000	NONRES	N	C		Installed after lead ban	N	1/25/23	Cross-connection survey	Field inspection only	Y	1/25/23	Cross-connection survey	duct/copper
009-0040-00	SUBWAY	2201 MADISON STREET	N																			
009-0050-00	910 Charles Street		N																			
009-0060-00	910 Charles Street		N																			
009-0070-00	UNIT 1 SALON & MORE LLC	668 MARATECH AVENUE,	N																			
009-0080-00	668 MARATECH AVENUE		N	DI	N	6"	2000	DI	2"	2000	NONRES	N	O	2000	Installed after lead ban	N	1/18/2023	Cross-connection survey	Diameter > 2 inches	Y	1/18/2023	Cross-connection survey	Duct/Pex
009-0090-00	ATTN: Accounting Dept.	1077 WILSHIRE BLVD.	N																			
009-0180-00	P.O. BOX 260		N	DI	N	6"	2000	P	1 1/2"	2000	NONRES	N	C	2000	Installed after lead ban	N	2/22/22	Cross-connection survey	Field inspection only	Y	2/22/22	Cross-connection survey	plastic/copper
009-0190-00	PO BOX 705		N																			
009-0191-00	PO BOX 141		N																			
009-0200-00	981 BLUE STONE LANE		N	C	N	1"	2000	C	1"	2000	NONRES	Y	O	2000	Installed after lead ban	N			Installed after lead ban	Y	7/26/2024	Visual insp at meter	Pex/Copper
009-0210-00	981 BLUE STONE LANE		N	C	N	1"	2000	C	1"	2000	NONRES	Y	O	2000	Installed after lead ban	N			Installed after lead ban	Y	7/26/24	Cross-connection survey	Pex/Copper
009-0220-00	BLUE STONE ESTATES NORTH	401 RANGER STREET	N																			
009-0220-01	BLUE STONE ESTATES NORTH	401 RANGER STREET	N																			
009-0230-00	BLUE STONE ESTATES SOUTH	401 RANGER STREET	N																			
009-0240-00	962 BLUE STONE LN		N	DI	N	6"	2022	DI	4"	2022	MF	N	C	2022	Installed after lead ban	Y	2022	Visual insp during install or repair	Installed after lead ban	Y	11/4/23	Visual insp during install or repair	ductal/copper pex
009-0240-01	962 BLUE STONE LN		N	DI	N	6"	2022	DI	4"	2022	MF	N	C	2022	Installed after lead ban	Y	2022	Visual insp during install or repair	Installed after lead ban	Y	11/4/23	Visual insp during install or repair	ductal/copper pex
009-0250-00	960 BLUE STONE LN		N	DI	N	6"	2022	DI	4"	2022	MF	N	O	2022	Installed after lead ban	Y	2022	Visual insp during install or repair	Installed after lead ban	Y	1/14/23	Visual insp at meter	ductal/copper pex
009-0290-00	580 MARATECH AVE		N	DI	N	6"	2022	DI	4"	2022	MF	N	C	2022	Installed after lead ban	Y	2022	Visual insp during install or repair	Installed after lead ban	Y	11/4/23	Visual insp during install or repair	ductal/copper pex
009-0290-01	580 MARATECH AVE		N	DI	N	6"	2022	DI	4"	2022	MF	N	C	2022	Installed after lead ban	Y	2022	Visual insp during install or repair	Installed after lead ban	Y	11/4/23	Visual insp during install or repair	ductal/copper pex
009-0420-00	550 MARATECH AVENUE		N																			
009-0440-00	530 MARATECH AVENUE		N																			
009-0460-00	500 Maratech Avenue		N																			
009-0510-00	497 MARATECH AVENUE		N																			
009-0520-00	498 MARATECH AVENUE		N	DI	N	8"	2000	DI	8"	2000	NONRES	N	C	2000	Installed after lead ban	Y	2000	Cross-connection survey	Installed after lead ban	Y	1/22/24	Cross-connection survey	ductal/copper pvc
009-0640-00	983 154TH AVE		N																			